

Company  
Well  
Field  
County  
State

CHAPARRAL ENERGY, LLC.  
NBU #10-18  
BURBANK  
OSAGE  
OKLAHOMA

**RECON**

CEMENT BOND  
VARIABLE DENSITY  
GAMMA RAY  
COLLAR LOCATOR

	SEC 11	TWP 27N	RGE 05E		OTHER SERVICES:
Location.	990' FSL & 625' FWL		N/A		DIL CNL
SURF. SAME		API#.	35-113-21339	LDT	SONIC
Permanent Datum	Ground Level	Elev	1168.13	ELEVATIONS	K.B. 1175.13 G.L. 1168.13 D.F. N/A

Date	30-JUN-2016			
Run No.	ONE			
PBTD	3110 ft.			
TD RECON	3124 ft.			
Bot Logged Interval	3122 ft.			
Top Logged Interval	50 ft.			
Casing Depth Driller	7 in.	@ 3017	in.	@
Casing Depth RECON	7 in.	@ 3017	in.	@
Bit Size	6 1/8 in.			
Drilling Fluid Type	WATER			
Density	8.3	N/A		
Fluid Loss	PH	N/A		
Source Of Sample	Flowline			
RM @ Measured Temp	N/A	Ohmm	@ N/A	Ohmm @
RMF @ Measured Temp	N/A	Ohmm	@ N/A	Ohmm @
RMC @ Measured Temp	N/A	Ohmm	@ N/A	Ohmm @
RM @ MRT	N/A	Ohmm	@ N/A	Ohmm @
Max Recorded Temp	N/A	DegF		DegF
Time Drilling Stopped	N/A	N/A		
Time Circulation Stopped	N/A	N/A		
Time Logger On Bottom	30-JUN-2016	17:07		
Unit Num	S408	OKLAHOMA CITY, OK		
Recorded By	H. GARCIA			
Witnessed By	MR. J. LILES			

All interpretations are based on inferences from electrical or other readings, and therefore, RECON cannot and will not guarantee the accuracy of any interpretations of log data. RECON shall not be liable for any loss, costs, damages, or expenses incurred or sustained by anyone resulting from interpretations made by any of our officers, agents or employees, except in the case of provable Gross Negligence or willful damage. Interpretations are also subject to the terms and conditions of our Price Schedule and General Service Agreement.

All interpretations are based on inferences from electrical or other readings, and therefore, RECON cannot and will not guarantee the accuracy of any interpretations of log data. RECON shall not be liable for any loss, costs, damages, or expenses incurred or sustained by anyone resulting from interpretations made by any of our officers, agents or employees, except in the case of provable Gross Negligence or willful damage. Interpretations are also subject to the terms and conditions of our Price Schedule and General Service Agreement.


RIG INFORMATION



Drill Contr/Rig#      GLOBE ENERGY SERVICES


GENERAL REMARKS SECTION


TIED INTO ??  
CNL / LDT LOG DATED 30-JUN-2016.

**BHC SONIC / GAMMA RAY /  
COMPENSATED NEUTRON / Y-CALIPER**









<< TENS

<< GR

CCL>>

<< TENS

GR>>

CCL>>

<< TENS



600


650


700


750


800
































### GAMMA RAY CALIBRATION

SERIAL NUM  
BLANKET NUM

RG3015\_CH3

1A

#### MASTER CALIBRATIONS

	BackGrnd	CalVal: 158.000 API	Gain/Offset	CALIBRATION DATE	CALIBRATION TIME
BASE CALS	52.152 - raw	380.790 - raw	0.481 - gain 0.000 - off	M/D/Y> 3/17/2016	H:M:S> 14:5:39

Company	CHAPARRAL ENERGY, LLC.
Well	NBU #10-18
Field	BURBANK
County	OSAGE
State	OKLAHOMA

CEMENT BOND  
VARIABLE DENSITY

RECON

**RECON**

**GAMMA RAY  
COLLAR LOCATOR**